

**NUMBER:** 08-034-06 REV. A

**GROUP:** Electrical

DATE: October 3, 2006

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 08-034-06, DATED SEPTEMBER 2, 2006, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH \*\*ASTERISKS\*\* AND INCLUDES ADDITIONAL MODELS.

#### SUBJECT:

StarSCAN® Displays A Red "X" For The Steering Angle Sensor (SAS) Module

### **MODELS:**

2007 **2007	(CS) (JK)	Pacifica Wrangler/Wrangler Unlimited**

NOTE: This bulletin applies to vehicles equipped with Electronic Stability Program (ESP) (sales code BNB).

#### **DISCUSSION:**

If the technician finds a red "X" displayed on the StarSCAN® ECU View screen, (Fig. 1), for the SAS perform the following:




Fig. 1 ECU View Screen



Attempt to access the SAS with the StarSCAN®.

• If able to access the SAS then the red "X" is erroneous and should be ignored.

# NOTE: Do not replace the BCM or the SAS for this issue.

• If not able to access the SAS then the SAS is truly not responsive and further diagnosis is necessary. Refer to the detailed diagnostic information available in TechCONNECT under: Service Info > 8-Electrical > Electronic Control Modules - Electrical Diagnostics > Lost Communication With SAS.

## **POLICY:**

Information Only.