



NUMBER: 23-041-06

GROUP: Body

DATE: September 27, 2006

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Exterior Lamp - Lens Fogging

MODELS:

2006 - 2007	(DC)	Ram Cab & Chassis
2006 - 2007	(DR/DH/D1)	Ram Truck
2006 - 2007	(HB/HG)	Durango/Aspen
2007	(JK)	Wrangler
2006	(JR)	Stratus/Sebring
2007	(JS)	Sebring
2007	(KA)	Nitro
2006 - 2007	(KJ)	Liberty/Cherokee
2006 - 2007	(LX/LE)	300/Magnum/Charger
2007	(MK)	Compass
2006 - 2007	(ND)	Dakota
2007	(PM)	Caliber
2006 - 2007	(PT)	PT Cruiser
2006 - 2007	(WK/WH)	Grand Cherokee
2006 - 2007	(XK/XH)	Commander

DISCUSSION:

Some customers may report that on occasion, vehicle exterior lamp assemblies are fogged with a light layer of condensation on the inside of the lenses. This may be reported after the lamps have been turned on and brought up to operating temperature, turned off, and then rapidly cooled by cold water (such as rain, or the water from a car wash). Lens fogging can also occur under certain atmospheric conditions after a vehicle has been parked outside overnight (i.e., a warm humid day followed by clear cool night). This will usually clear as atmospheric conditions change to allow the condensation to change back into a vapor. Turning the lamps on will usually accelerate this process.

A lamp that has large amounts of water droplets visible on most internal surfaces indicates a problem with the lamp sealing that has allowed water to enter the lamp. In this instance, the customer is likely to report that moisture in the lamp is always present and never disappears. A lamp that exhibits internal moisture permanently should be replaced.



Stick with the Specialists™

POLICY:
Information Only